

FOTECOAT 1920 K CERAMIC

1. Description

- Fast, duo-cure polymer type textile printing screen process emulsion with separate diazo sensitizer powder, for aqueous ink systems.
- Light blue color with excellent see-through.
- The ready-made stencil can be post-hardened by light to increase the mechanical and the solvent resistance.
- Very short exposure time.
- Ecologically sound.

2. Application advantages

- 44% solids content before sensitizing.
- Low viscosity, appropriate for meshes between 43-80 and 120-34 (lower viscosity than FOTECOAT 1065 and a higher viscosity than FOTECOAT 1636).
- FOTECOAT 1920 K is a water resistant emulsion that can be printed with most inks containing water and little solvents.
- A longer exposure renders the stencil more resistant against abrasion and therefore allows to print longer runs.
- FOTECOAT 1920 K can be decoated.
- If a permanent stencil for all inks is desired a longer post-hardening by light or a chemical treatment with FOTECHEM 2110 or 2100 Hardener can be used. In such a case the stencil can no longer be decoated.

3. Coating technique and stencil build-up

It is recommended to let degas the emulsion after sensitizing during a few hours.

<u>Mesh</u>	<u>Coating</u>	<u>Stencil build-up</u>
43-80	1/1	20 μ
77-55	1/2	15 μ
120-34	1/1	6 μ
120-34	1/2	10 μ

FOTECOAT 1920 K is ideal for machine coating. If necessary the emulsion can be diluted with water.

4. Stencil quality

- The definition is excellent. The high solids content allows to reach a flat stencil surface combined with excellent mesh bridging.
- The resolution is good.

5. Stocking

- Unsensitized: up to 1 year
- Sensitized at 20°C: 1 - 2 weeks
- Pre-coated screens stored in complete darkness at 20°C: 3 weeks

6. Exposure times

5 KW metal halide lamp at 100 cm distance; iron charged high pressure burner at 100 hours burning time.

<u>Coating</u>	<u>Mesh</u>	<u>Time in seconds after complete drying</u>
1/1	43-80 white	90
1/2	43-80 white	120
1/1	43-80 yellow	135
1/2	43-80 yellow	180
1/1	77-55 white	70
1/2	77-55 white	90
1/1	120-34 white	45
1/2	120-34 white	60
1/1	120-34 yellow	70
1/2	120-34 yellow	90

7. Decoating

- Only possible with high pressure gun.
- A higher concentrated remover than usual has to be used. Ideal are FOTECHEM 2004 liquid or FOTECHEM 2005 paste.
- For machine decoating the concentration of the remover liquid has to be increased and the speed of the machine be reduced to a minimum.
- A post-exposure makes the stencil removal easier.

8. Post-exposure

Once the stencil is washed-out and dried it can be exposed again under the sun, day light fluorescent tubes or with the standard exposure lamp; it is recommended to make the post-exposure without the vacuum frame so that no glass between the lamp and the stencil interferes with light absorption.

FOTEC AG

These Technical Informations are published without warranty. The results shown in these Technical Informations are based on laboratory testing. The supplier declines any responsibility for incorrect use of these products which are manufactured and sold for industrial use only.